


Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	232	713/164.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:23
S2	31	S1 and BIOS	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/19 11:27
S3	3	S1 and BIOS same password	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:23
S4	4	kernel same BIOS with password	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/19 12:40
S5	5	unlock with hard adj drive with password	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:08
S6	148	BIOS same kernel same driver	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/20 07:08
S7	1148	713/202.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:23
S8	73	S7 and BIOS same password	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:23
S9	0	S7 and BIOS same password same kernel	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:23

S10	7	S7 and BIOS same password and kernel	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:23
S11	2	password with BIOS same unlock with hard adj drive	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:34
S12	9	VANDER near KAMP near KERRY	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/20 07:34
S13	0	fast with boot with kernel with flash	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/25 14:42
S14	177	kernel with flash	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/25 14:42
S15	49	kernel with flash with operating adj system	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/25 14:43
S16	47	request\$4 with bios with password	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/26 06:55
S17	1	secure near mode same maintenance near mode same hard adj (drive disc disk)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/26 09:48
S18	13	secure same maintenance same hard adj (drive disc disk)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/26 07:25
S19	1	intrusion same maintenance same hard adj (drive disc disk)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/26 07:25

S20	2	secure near mode same maintenance near mode same (system computer)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/26 09:49
S21	9	secure with mode same maintenance with mode same (system computer)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/26 09:49



Web Images Groups News Froogle Local^{New!} more »

ATA security freeze lock unlock BIOS dateranSearch Advanced Search Preferences

Web Results 1 - 10 of about 1,640 for **ATA security freeze lock unlock BIOS daterange:2449718-2452264** (

[Ports List, part 2 of 3 Copyright \(c\) 1989-1999,2000 Ralf Brown ...](#)

... FFh IDE vendor vend vendor unique 4 F5h **Security Freeze Lock** F6h **Security Disable**

Password SeeAlso: #P0512,#P0514 Format of IDE/ATA Identify Drive ...

bochs.sourceforge.net/techspec/ralfbrown/PORTS.B - 101k - Supplemental Result - [Cached](#) - [Similar pages](#)

[\[doc\] ATA Extensions Document](#)

File Format: Microsoft Word 6 - [View as HTML](#)

... The following is a proposal for inclusion into ATA/ATAPI-4 of additional explicit rules for determining the cylinder/head ... **SECURITY FREEZE LOCK**. ... **SECURITY UNLOCK**. ...

www.t13.org/technical/d97119r2.doc - Supplemental Result - [Similar pages](#)

[\[doc\] FLUSH CACHE](#)

File Format: Microsoft Word 2000 - [View as HTML](#)

... It allows a BIOS/Driver to get exact information and allows for a quick assessment of supports ... 2. 1 = supports ATA-2. 1. ... 1 = supports **Security Mode** feature set. 0 ...

www.t13.org/technical/e00144r1.doc - Supplemental Result - [Similar pages](#)

[More results from www.t13.org]

[\[PDF\] DK23AA-12/90/60 Disk Drive Specifications REV.3](#)

File Format: PDF/Adobe Acrobat - [View as HTML](#)

... 79 6.3.2.9.9 **Security Freeze Lock** [F5h ... 80 6.3.2.9.11 **Security Mode Command Action** [F1h ... Physical/Electrical Interface: ATA-5 -Handling : Do not add Electrical ...

d0.web.lal.in2p3.fr/L2BETA/ components/Harddrive/HardDrive.pdf - Supplemental Result - [Similar pages](#)

[\[PDF\] Maxtor 536DX](#)

File Format: PDF/Adobe Acrobat - [View as HTML](#)

... Set **Max Freeze Lock** ... Multiple Mode This mode is implemented per ANSI ATA/ATAPI-5 ... Automatic Park and **Lock** Operation Immediately following power down, dynamic ...

www.saidsystems.com/Products/D540X-4D_pm.pdf - Supplemental Result - [Similar pages](#)

[\[PDF\] NAGASAKI IPC TECHNOLOGY](#)

File Format: PDF/Adobe Acrobat - [View as HTML](#)

... product complies with 40/44 PIN IDE (ATA) ... **BIOS** Settings (see specification) Capacity Cylinders Heads Sectors ... blocks, the device will be **locked** automatically to ...

sta.bwi.com/upload_data/documents/DOM_TDK_datasheet.pdf - Supplemental Result - [Similar pages](#)

[Linux Kernel mailing list Archive: Nach Autor](#)

... 14 (21.11.2001). Re: updates for ata/atapi hosts ... 2001). Re: [CHECKER] 8 probable **security** errors (03.11 ... Lopes: UPDATE - Re: System temporary **freeze** (but network ...

www.stunet.tu-freiberg.de/~hypermail/lkml/2001/11/author.html - 101k - Supplemental Result -

[Cached](#) - [Similar pages](#)

[\[RTF\] Section 1](#)

File Format: Rich Text Format - [View as HTML](#)

... 09/18/00 (Laptop **security** cable **lock** with motion sensor) CUST ... DVD ROM SD-C2202 AND UNDER IDE/ATA CONTROLLERS AS A ... 2 CABLE AND THE SYSTEM DID NOT **FREEZE** WHEN HE ...

asgard.kent.edu/internships/ Kaltenbach/kaltenbach.activity.log.rtf - Supplemental Result - [Similar pages](#)

[\[PDF\] MPF3xxxAT DISK DRIVES PRODUCT MANUAL](#)

File Format: PDF/Adobe Acrobat - [View as HTML](#)

... 5 - 62 5.13 Relationship between combination of Identifier and Security level, and operation of the lock function ... ATA-4 (Maximum Cable length: 0.46 m) ...

www.fdg.fujitsu.com/support/disk/manuals/pb15_pm1.pdf - Supplemental Result - [Similar pages](#)

[linux-kernel ML](#) - [[Translate this page](#)]

... 02] Updated modutils fixing local root security bug available ... Garzik <jgarzik@mandrakesoft.com>; Re: Freeze on FPU ... ATA/IDE: dmaproc error 14 testers wanted!Andre ... search.luky.org/linux-kernel.2000/mail16.html - 101k - Supplemental Result - [Cached](#) - [Similar pages](#)

Google ►

Result Page: [1](#) [2](#) [Next](#)

Free! Google Desktop Search: Search your own computer. [Download now.](#)

Find: [emails](#) - [files](#) - [chats](#) - [web history](#) - [media](#) - [PDF](#)

[Search within results](#) | [Language Tools](#) | [Search Tips](#) | [Dissatisfied? Help us improve](#)

[Google Home](#) - [Advertising Programs](#) - [Business Solutions](#) - [About Google](#)

©2005 Google